

FIG. 2




FIG. 3A

$$P = \begin{bmatrix} 0.268 & 0.881 & 0.119 & 0.119 & 0.881 & 0.5 \end{bmatrix}$$

$$H = \begin{bmatrix} 1 & 1 & 0 & 1 & 0 & 0 \\ 0 & 1 & 1 & 0 & 1 & 0 \\ 1 & 0 & 1 & 0 & 0 & 1 \end{bmatrix}$$

FIG. 3B

$$\mathbf{Q} = \begin{bmatrix} 0.268 & 0.881 & 0 & 0.119 & 0 & 0 \\ 0 & 0.881 & 0.119 & 0 & 0.881 & 0 \\ 0.268 & 0 & 0.119 & 0 & 0 & 0.5 \end{bmatrix}$$

FIG. 3C

$$R' = \begin{bmatrix} 0.119 & 0.119 & 0 & 0.268 & 0 & 0 \\ 0 & 0.119 & 0.881 & 0 & 0.119 & 0 \\ 0.119 & 0 & 0.268 & 0 & 0 & 0.119 \end{bmatrix}$$


FIG. 3D

$$R = \begin{bmatrix} -0.119 & -0.119 & 0 & -0.268 & 0 & 0 \\ 0 & -0.119 & -0.881 & 0 & -0.119 & 0 \\ -0.119 & 0 & -0.268 & 0 & 0 & -0.119 \end{bmatrix}$$

FIG. 3E

$$\mathbf{Q'} = \begin{bmatrix} 0.149 & 0.762 & 0 & 0.119 & 0 & 0 \\ 0 & 0.762 & -0.149 & 0 & 0.881 & 0 \\ 0.149 & 0 & -0.762 & 0 & 0 & 0.5 \end{bmatrix}$$

FIG. 4






FIG. 6




FIG. 7

